ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
7

Ward Name
Byatarayanapura

Street ID
W0821, W0634, W0825, W0829, W0833, W0630, W0837

Street Name
NA

Significant Landmark
Venkategowda layout cross roads

Segment No.
7/C-W0821/S114406

Total Length (m)
230.10

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	46.05	77.600427	13.053610	77.600501	13.054020	DEAD END	DEAD END
2	59.03	77.600155	13.053659	77.600239	13.054186	DEAD END	W0630
3	49.41	77.599863	13.053697	77.599952	13.054135	DEAD END	DEAD END
4	51.40	77.599588	13.053745	77.599680	13.054201	DEAD END	DEAD END
5	24.21	77.599350	13.054061	77.599397	13.054275	W0634	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of Concrete Roads in Venkategowda layout cross roads in ward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Construction of Concrete Roads in Venkategowda layout cross roads in ward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone

Job No. / Work Code
007-15-000018

Work Order No.
EE/BTP/BBMP/E-PMT/263/2014-15

Work Order Date
02/02/2015

Period of Extention
60 DAYS

Defect Liability Period From
02/02/2015

Defect Liability Period To
01/02/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

B M MUNIRAJU 0.00

Phone No. **E-Mail ID**

9886778826

Field Inspection Details

Number of Trees	Any Other Information	Name
0		BASAVARAJU
Date of Inspection	**Remarks**	
26/11/2016	Completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0821, W0634, W0825, W0829,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/11/2016	25/12/2016	COMPLETED
SE	VASU K M	27/11/2016	25/12/2016	COMPLETED
EE	SRINIVAS REDDY	27/11/2016	25/12/2016	COMPLETED
AEE	RAJINIKANTH MALLI	27/11/2016	25/12/2016	COMPLETED
AE	BASAVARAJU	27/11/2016	25/12/2016	COMPLETED
AE	BASAVARAJU	26/11/2016	25/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0821, W0634, W0825, W0829,